


# AX Screw Types

## Conversion from Guage to Metric


GUAGE	MM
2g	2.2mm
4g	2.8mm
6g	3.5mm
8g	4.2mm
10g	4.8mm
12g	5.5mm
14g	6.3mm
16g	6.8mm
18g	8.0mm

## Screw Heads

Countersunk Bugle Hex Hex Washer Wafer Undercut



Pan Button Crop Top Mush Oval Cap



## Screw Drives

### COMMON



### SECURITY




## Screw Points



### Self Drilling Screw

Drilling point that will drill through metal.



### Type 17

A thread cutting screw for wood with a coarse screw thread and a long sharp point fluted to capture chips.



### Dual Point

Dual point screws are made especially to screw into both timber and metal.



### S500

Extended drill points for screwing into thick metals.



### Self Tapping Screw

A thread forming screw with coarse thread for use in thin metal.



### S-Point or Self Piercing Point

Produces more secure sheet metal assemblies. These are also known as a needle point, speed points or sprint points.